

Corrigendum – I dated 02/08/2023

To

**STRUCTURAL REPAIRS AND ALLIED WORKS IN C, D, DX & E TYPE FLATS
IN MMTC HOUSING COLONY, NEW DELHI**

In the BOQ, POINT NO 4 is modified as below:

Point No	Existing	Unit	Modified	Unit
4	Making up lost section of concrete / mortor with thixotropic repair mortor is one component thixotropic dual shrinkage compensated fiber reinforcement formulation for structural members. Build up section by hand packing as per manufacturers specification , applied by mean of hand glouse by expert applicator, the rehabilitated surface should be free from air gaps, voids should be in line with existing required line and line with existing surface, including curing, cleaning the area etc. complete. The work should be carried out with all the safety measures like helmet, safety belt and adequate labour insurance under the supervision of qualified supervisor etc. complete.	Sqm	Making up lost section of concrete / mortor with thixotropic repair mortor is one component thixotropic dual shrinkage compensated fiber reinforcement formulation for structural members. Build up section by hand packing as per manufacturers specification , applied by mean of hand glouse by expert applicator, the rehabilitated surface should be free from air gaps, voids should be in line with existing required line and line with existing surface, including curing, cleaning the area etc. complete. The work should be carried out with all the safety measures like helmet, safety belt and adequate labour insurance under the supervision of qualified supervisor etc. complete.	Kgs

All other terms and conditions of the tender shall remain the same.

This Corrigendum becomes an integral part of the notice (NIT) NO. MMTC/Estate/SO/SA/1006/2022-23 DATED 19TH July 2023 for STRUCTURAL REPAIRS AND ALLIED WORKS IN C, D, DX & E TYPE FLATS IN MMTC HOUSING COLONY, NEW DELHI